LIST OF REFERENCE CHARACTERS

| Numerically controlled machine tool |
|--------------------------------------|
| Spindle support structure |
| Extended spindle support structure |
| Workpiece support structure |
| Extended workpiece support structure |
| Chip discharge means |
| Base |
| Extended base |
| Movable body |
| Beam |
| Bed |
| Column |
| Longitudinal space |
| Extended longitudinal space |
| Opening |
| X-axis slider |
| Y-axis slider |
| Z-axis slider |
| Through opening |
| Extension |
| X-axis guide |
| Slide element |
| Mover |
| |

| 49 | Stator |
|----|------------------------|
| 51 | Y-axis guide |
| 53 | Y-axis slide element |
| 55 | Nut |
| 57 | Ball screw |
| 59 | Z-axis guide |
| 61 | Z-axis slide element |
| 63 | Z-axis motor |
| 65 | Non-contact wiper |
| 67 | Non-contact wiper |
| 69 | Contact wiper |
| 71 | Contact wiper |
| 73 | Spindle head |
| 75 | Spindle |
| 77 | Rotational axis |
| 79 | Swivel base |
| 81 | Swivel motor |
| 83 | Gear |
| 85 | C-axis motor |
| 86 | Direction along A-axis |
| 87 | Direction along C-axis |
| 89 | Workpiece |
| 91 | Base |
| 93 | Shaft support means |
| 95 | Rotating shaft |

| 97 | Arrow |
|--------------------|----------------------------|
| 99,99',99" | Workpiece mounting table |
| 101,101' | Pushing means |
| 103,103a,103b,103c | Workpiece mounting surface |
| 105 | Pallet |
| 107 | Servo motor |
| 109 | Gear |
| 111 | Nut |
| 113 | Push screw |
| 115 | Depression |
| 117 | Roller |
| 119 | Pallet changing means |
| 121 | Pallet stocker |
| 123 | Pallet carrier |
| 125 | Z-axis guide rail |
| 127 | Carrier Base |
| 129 | X-axis guide rail |
| 131 | Setup station |
| 133 | Means for rotating |
| 135 | Pallet mounting means |